




EMMYWATCH
VINTAGE RESTORATIONS

Record 110,111,112,114 Movement Parts (1)

Compiled by EmmyWatch - <https://www.emmywatch.com>


RECORD WATCH Co. S. A.

PIÈCES DE RECHANGE — ERSATZTEILE
 EXCHANGE PARTS — PIEZAS DE REPUESTO




No. 110



Cal. 8 ³/₄ - 12'''



No. 111



No. 112



No. 114



1101



1102



1103



1104



1105



1106



1107



1108



1109



1110



1111



1112



1113



1114



1115



1116



1117



1118



1119



1120



1121



1122



1123



1124



1125



1125^a



1126



1126^a



1127



1127^a



1128



1129



1130



1131



1132



1132^a



1133



1133^a



1134



1135



1136



1137



1138



1139



1140



1141



1142



1143



1144



1145



1146



1147



1148